

MODELS LC26SA1E LC26SD1E LC32SA1E LC32SD1E LC42SA1E
 LC42SD1E

SYMPTOM The following symptoms may be apparent:

- Sound, no picture
- Various operational key issues

CAUSE Software issues.

ACTION Update main software to the latest version, following the instructions in the service manual.

Sharp Electronics (UK) Limited

Reference – LV 195
Revision - 1

White – Carry out as required
Yellow – Carry out as required and whenever the unit comes in for service
Red – Carry out on all units